

Service Dealer Guide 2005



DORMAN **HELP!** **DORMAN**
OE Solutions



100% NEW Brake Caliper Assemblies



Exhaust Manifold Kits



Clock Springs



Harmonic Balancers



Heater Hose Assemblies



NEW Ignition Distributors



Intake Manifold Kits



Oil Pans



Fuel Lines



NEW 4WD Components



Air Intake Hoses



Oil Cooler Line Assemblies



Power Steering Pulleys



Quick Disconnect™



Fuel Sending Units



Radiator Fan Assemblies



Wiper Transmission Linkages



Rear Axle Shaft Kits



Window Regulators & Lift Motors



Timing Cover Kits



NEW Wiper Motors



Transmission Lines



A/C Bypass Pulleys



Fluid Reservoirs



Conduct-Tite! Electrical Tools & Accessories



Exhaust Manifold Bolt Kits



Radiator Overflow Tube Repair Kit



NEW Wiper Pulse Boards



Distributor O-Rings



Temperature Blend Door



Tail Lamp Circuit Boards



Window Switches



Door Lock Actuators



Wiper Arms



Fuel Pressure Regulators



Door Hinge Assemblies



Tech Trays



Oil Drain Plugs



Wheel Studs & Nuts



Spindle Hardware



Brass Fittings, Hoses & Tubing



Cotter Pins, Washers & Screws



Body Hardware

DID YOU KNOW ?

THESE WERE AVAILABLE IN THE AFTERMARKET ?



DHP24011
Dorman Hard Parts Catalog

2500015
Dorman Automotive Assortment Guide

MM24010
Motormite Catalog

2500019
Dorman Hard Parts Supplement

2500021
Dorman Automotive Hardware Catalog

2500020
Motormite Supplement

DORMAN ENGINEERED



INTAKE MANIFOLD KITS RE-ENGINEERED TO PREVENT COMMON FAILURE PATTERNS



615-176
4.0L SOHC Ford Explorer,
Mountaineer
2001-97

Integrated Square Port Gasket
Design for Easier Manifold
Installation.




Includes
Thermostat,
Gaskets and
Brackets



615-175
4.6L Ford
Square Port
2004-99
Patent Pending



Reinforced Aluminum Crossover
eliminates repeat failure due to
corrosion or vibration.



OE Manifold Affected Area
The Plastic Throttle Body Coolant Passage is corroded
by EGR gases and coolant, causing leakage into engine.

OE Solutions Improved Intake Manifold
has 5x greater reinforced wall material in
failure-prone area for greater durability.



615-180
3.8L GM Series II
2004-95



Patent
Pending

615-178
4.6L Ford
2000-96



615-179
3.8L GM Series I
1995-93



615-182
4.3L GM Vortec®
2004-96




615-181
5.0L, 5.7L GM
Vortec® 2004-96

Vortec® is a registered trademark of
General Motors Corporation.

FUEL LINES & CONNECTORS

FORD FOCUS FUEL LINE



**SAVES
2 HOURS
OF
LABOR
TIME**



**SAVE
85%***

***Dorman Quick Disconnect™ Replacement Part: \$23 at Dorman Dealer Price
OE Assembly: \$165 at OE Wholesale Price**

Ask Your Distributor for
the Latest Quick Disconnect™
2500000 Reference Poster

ADDITIONAL FUEL LINE COVERAGE

800-840 GM K-Series Pickup 1995-88	800-857 Ford Taurus 1999-96	800-858 Ford Taurus 2000	800-859 Ford Taurus 2001	800-860 Ford Taurus 2002



TOYOTA CAMRY FUEL LINE



Complete Quick Disconnect™ Coverage for All Your Oil, Fuel, Transmission & Heater Hose Applications

TRANSMISSION & OIL CONNECTORS

COOLING SYSTEM QUICK CONNECTORS

■ Compact design includes wrench flats for easy use



800-408 Removal Tool
Use with 800-401 & 800-402

■ Removes broken GM Coolant Connectors




GM Cars & Trucks
2002-90



**DO THE
JOB
RIGHT!**



FUEL LINE REPAIR KIT



PAYS FOR ITSELF IN TWO JOBS

Features



Kit features superior professional quality tool with ergonomic clamp type grip



Innovative clamp block design makes joining nylon to nylon barbed fittings easy



Two 10' rolls of nylon tubing included



Includes straight and elbow connectors to tackle the most popular applications



High quality cutter makes trimming nylon tubing easy



Innovative elbow and straight connector holders for use with most applications



Easy-to-use nylon to nylon and nylon to steel compression fittings included

BEFORE



- OE fuel lines are cumbersome and difficult to install
- Bay time is wasted waiting for an assembly you don't have in stock
- Hours of shop time and labor are wasted replacing multiple line assemblies, when just a small section needs to be repaired

AFTER



- Fuel Line Repair Kit saves time—no more difficult manipulation of entire steel fuel lines
- No more wasted bay time—always have the line you need on hand
- Fuel Line Repair Kit gives you the ability to fabricate custom fuel lines on demand
- Increase customer satisfaction by repairing only the damaged section



Visit us at www.DormanProducts.com ■ Call Our New Product Hotline 1-800-336-3575

NEW TO THE AFTERMARKET

CLOCK SPRINGS

EASY TO INSTALL



For a Video of "How To Install Clock Springs"
Visit Our Website www.DormanProducts.com/video.shtml

- Clock Springs Fail When Wire Breaks or Separates From the Connector
- When Wire Controlling Air Bag Fails Warning Light Illuminates
- One On Every Vehicle Since 1994
- Program Covers the Most Failure-prone Applications



Direct OE Replacement



Recommended Replacement With Every Air Bag Deployment



525-100
Chrysler Minivans
w/cruise
2000-96



525-200
Ford Bronco,
F-Series Pickups
1994

Look For
Additional
Applications
This Summer!



525-101
Chrysler Minivans
2005-01



525-106
Chrysler Minivans
w/o cruise
2000-96

TECH TIP

When any suspension/ steering repairs are performed on a vehicle equipped with an air bag system, the steering wheel **MUST** be locked in the neutral (center) position. If not, the wheel can rotate and cause the air bag spring to be wound too tight in one direction. Then when the first turn is made, the Clock Spring will snap. The result is an open circuit in the system that will cause the air bag light to come on and the system will be inoperative. *NOTE:* The air bag system is constantly monitored and will shut off when it senses an open air bag circuit.



AIR INTAKE HOSES

696-100 GM S10 Blazer/ Pickup 1995-92	696-200 Ford/Mazda 1996-90	696-201 Ford/Mazda 1992-90	696-600 Mazda Protégé 1996-95	696-602 Mazda 626, MX6 1997-93	696-603 Mazda MVP 1995-93	696-605 Mazda Millennia 2002-95	696-700 Toyota Camry 1995-92

NEW CATEGORY!

FLUID RESERVOIRS

603-101 GM G-Series Vans Coolant 1991-84	603-200 Ford Taurus, 12V Coolant 1999-96	603-201 Ford Taurus, 24V Coolant 2003-96	603-202 Ford Escort Washer 1990-84	603-301 Nissan Maxima Washer 2003-94	603-600 Chrysler LHS Coolant 1997-93	603-601 Nissan Altima Washer 2001-94

NEW CATEGORY!

POWER STEERING PULLEYS

300-003 Ford Taurus, Aerostar, Mercury Sable, Bronco, F-Series, 2004-85	300-201 GM 2004-93	300-306 Jeep Cherokee 1998-94	300-308 Dodge Intrepid 2004-98; Plymouth Prowler 2002-98

EXTENDED COVERAGE!



HAVE YOU EVER SEEN THIS?

- Power Steering Pulleys Bend and Break During Removal
- Order the Power Steering Pulley When you Order the Pump

AIR INTAKE HOSES

Cracked or Worn Air Intake Hoses Allow Unmetered Air into the Engine Causing:



- Engine to Stall Out
- Poor Gas Mileage
- Rough Idle
- Sluggish Acceleration

- Check for Cracks and Dry Rot During Inspections

FLUID RESERVOIRS

- Direct OE Replacement



- All Dorman OE Solutions Reservoirs Include Caps—the OE Dealer Only Offers Them Separately

POWER STEERING PULLEYS

- Coverage Includes Light Truck, SUV & Imports

MARKET LEADING COVERAGE

RADIATOR FAN ASSEMBLIES

DROP-IN REPLACEMENT

- 228 SKUs Cover the Most Failure-Prone Vehicles
- Additional Late Model & Import Coverage



Pre-assembled

- Saves Time & Money



OE Un-assembled
1+ Hours of Labor



Dorman Pre-assembled
Save \$75 on Labor

Direct OEM Replacement

- Dorman Motor & Wire Harness Connectors Match OEM for Perfect Fit

OEM



Dorman
#620-531



620-636
Buick LeSabre
2005-00



620-131
Ford Windstar 2003-99

620-419
Nissan Altima 2005-02



EXHAUST MANIFOLDS KITS



- 240 Manifolds Cover 86 Million Vehicles On the Road
- New Coverage Includes Import, Light Truck & SUV Coverage
- Dorman Exhaust Manifold Kits Include Flange and the Necessary Hardware & Gaskets for a Complete, Professional Installation



The Dorman Advantage

Dorman Provides OE Style Hardware and OE Quality Gaskets Packaged in a Separate Box For Protection.

Competitor's Loose Gaskets Are Often Damaged by The Manifold In Shipping.



Dorman Provides the Most Comprehensive Line of Exhaust Manifolds in the Aftermarket.

Most Dorman Exhaust Manifold Kits Include the Required Heat Shield(s), and Related Hardware.



HARMONIC BALANCERS

- 133 SKUs Covering 150 Million Vehicles on the Road
- Dorman Harmonic Balancers Include All the Necessary Hardware



100% **NEW**

WINDOW LIFT MOTORS

Install With Confidence Using 100% New Dorman Window Lift Motors

Don't Worry About Doubling Your Labor Cost After You Discover the Reman Motor Is Bad

Inconsistent Re-manufactured Quality Can Cost You Bay Time

Dorman 100% NEW Job Time	Potential Reman Job Time
1.5 HOURS	3.0 HOURS

Don't Worry About Your Customer Seeing Smoke

REMAN LABEL WARNING:




NOTICE: Do not be alarmed, smoke coming from motor is due to fresh paint. Condition is normal. Allow 1 hour of operating to clear smoke.



Sealed Pancake Motor Design

Don't Worry About Wasting Time Cutting Wires

DORMAN **COMPETITOR**



No wires

Wiring Harness included



742-247
Ford Mustang Convertible RF
1993-84

742-246
Ford Mustang Convertible LF
1993-84
(not shown)



742-344
Dodge Caravan,
Plymouth Voyage,
Chrysler Town & Country LF
2000-96

742-343
Dodge Caravan,
Plymouth Voyage,
Chrysler Town & Country RF
2000-96
(not shown)



Dorman Window Lift Motors are manufactured in QS 9000, ISO 9001 and ISO/TS 16949 certified facilities.


WINDOW REGULATORS & ASSEMBLIES



740-825
VW Jetta RF
1998-92



740-826
VW Jetta LF
1998-92



Includes Door Panel Clips, Panel Fasteners, Rivets And Dielectric Grease Where Needed.

Features

- **73% More Coverage** than Other Aftermarket Competitors
- Market Leading Coverage: **146 Total SKUs** for Most Popular Import and Domestic Applications

DORMAN Gives You A Choice

Motor Only



Regulator Only



Regulator with Motor



100% NEW IGNITION DISTRIBUTORS

Coverage for 12 Million Registered Vehicles



690-121
Nissan Altima 2.4L
1996-93

OE Failure #1

Misfiring Or Stalling in Extreme Hot or Cold Because of Outdated Electronic Ignition Design

Dorman Solution

Dorman IC Module Re-engineered Using the Latest Embedded Circuit Technology for Precise Spark Timing



OE Failure #2

"No Start" Condition Caused by Oil Leaking into Distributor Due to Worn Housing Seal

Dorman Solution

Dorman Housing Seal Redesigned with an Extra Lip to Provide a Barrier Against Oil Intrusion



Additional Ignition Distributors



690-132
Toyota Corolla
1993-90

690-133
Nissan
200SX,
Sentra
1998-95

690-902
Chevrolet/
GMC Trucks
& Vans
2000-96

Features

- Expanded Import Coverage
- Distributor Cap and Rotor Included for "Drop In" Unit Repair
- Reduce Comebacks Due to Reman
* suggested dealer price

Dorman® Price Advantage*

OE Part Complete Assembly	Aftermarket Rebuilt				Dorman Part Complete Assembly
	Remanufacturer			Total Complete Assembly	
	Distributor	Cap	Rotor		
\$481.16	\$355.30	\$16.36	\$5.24	\$376.90	\$338.32

100% NEW WIPER MOTORS

Market Leading Coverage

Dorman average weighted dealer price is

45%

less than average OE wholesale, and about the same price as Reman.



601-109
Various Models w/pulse
1994-84

601-112
Various Models
1996-84

601-113
Various Models
2002-84

601-300
Various Models
1995-89

AVOID COMEBACKS

Avoid comebacks from inconsistent reman quality. Would you want your customers to see smoke?



REMAN

REMAN LABEL WARNING:

NOTICE: Do not be alarmed, smoke coming from motor is due to fresh paint. Condition is normal. Allow 1 hour of operating to clear smoke.

100% NEW 4WD COMPONENTS

Features

- Direct OE Replacement
- All Mounting Brackets Included for Proper & Complete Installation.
- NEW Assemblies: No Core, Better Value.
- Dorman Suggested Dealer Price Average **24% Less** than OE Wholesale



600-900
Transfer Case Motor
GM Blazer, S10 Pickup,
GMC Truck S15, Jimmy Sonoma,
Typhoon, Typhoon 1993-92

600-800
Transfer Case Motor
Ford, Bronco II, Explorer,
Ranger 1995-90

600-100
4WD Actuator
GM Pickups & Suburban
w/ Over 8500 Lb
GVW 1995-92

Visit us at www.DormanProducts.com ■ Call Our New Product Hotline 1-800-336-3575


100% NEW



DORMAN
OE Solutions

100% NEW

100% NEW BRAKE CALIPERS




**DON'T
TRUST**

**YOUR
CUSTOMER'S
CAR**



**WITH
ANYTHING
BUT
NEW**



- OE and Remanufactured GM "W-Body" Calipers Use Steel Guide Sleeves, Which Cause Corrosion and Seizing
- Dorman® Units Prevent Corrosion and Seizing by Utilizing an Anodized Aluminum Guide Sleeve

- All Dorman® Calipers are Fully Assembled and Friction Ready
- Zinc Chromate Plating Extends Part Life and Reduces Corrosion



DON'T CALL THE OE DEALER

TIMING COVER KITS

2X DOUBLED OUR COVERAGE



635-400
1991-70
Dodge Passenger Cars
& Light Trucks



**GASKETS
& SEALS**
included when needed

Features

- OE Quality Backed by Dorman® Lifetime Warranty
- Includes Oil Pump When Pump is Integral Part of Timing Cover
- Expanded Coverage for the Most Failure-prone Parts

OE DEALER LIST PRICE	\$195.00
GASKET	\$12.20
SEAL	\$11.25
TOTAL	\$218.45

DORMAN DEALER PRICE ... **\$122.00**

SAVE 44%

REAR AXLE SHAFT KITS

29 Part Numbers

One-Piece Design

Quality OE Replacement



Rolled OE Spline Design

35% Stronger than Cut Spline Process




Axle Kit Includes:

- Axle Bearing
- Oil Seal
- Serrated Bolts
- Wheel Nuts



630-209

Ford Country Squire,
Crown Victoria, LTD,
Lincoln Continental,
Mark VI, Town Car,
Mercury Colony
Park, Grand
Marquis and
Marquis
1989-79



630-205

Ford Crown
Victoria, Lincoln
Town Car, Mercury
Grand Marquis
2002-98

DO IT RIGHT THE FIRST TIME

	Axle	Bearings	Wheel Seals	Wheel Hardware	Total	Warranty
OE Price	\$294.22	\$26.54	\$3.88	\$19.30	\$340.48	12 Month 12,000 Mi.
Dorman Dealer Price 630-209	Included	Included	Included	Included	\$190.00	2-Year Warranty

**SAVE
44%**

OIL PANS

57 of the Most Failure-Prone Pans Cover 95% of the Market

Includes Drain Plug and Seal
Corrosion Resistant Galvanized Steel



264-002
Ford Trucks
& Vans
1996-80

264-300
Toyota Celica
& Corolla
1993-88

264-403
Honda Accord
& Prelude
1997-90



E X C L U S I V E



264-200
Dodge Neon, Plymouth Breeze,
Chrysler Cirrus, Dodge Stratus
2004-95

BROAD COVERAGE


Including 3 aftermarket cast aluminum exclusives

264-101 GM Beretta, Cutlass Calais & Supreme, Grand Am, Grand Prix, Skylark 1991-87

264-102 GM Beretta, Cutlass Calais & Supreme, Grand Am, Grand Prix, Skylark 1994-87

FUEL SENDING UNITS

70+ of the Most Failure-Prone Units Cover 90% of the Market



692-003
GM 6000, Celebrity,
Century, Ciera 1992-89

692-000
GM C/K-Series
Pickups 1995-88

692-005
GM Blazer, Jimmy,
S-Series 1991-85

692-004
GM Blazer, Jimmy,
S-Series, Typhoon
1994-92

DORMAN AVERAGE DEALER PRICE IS
45% LESS THAN AVERAGE
OE WHOLESALE

INCLUDES:

- Locking Ring Set
- Strainer
- Hardware (where applicable)

TECH TIP

DO THE JOB RIGHT THE FIRST TIME

Fuel Sending Units are prone to corrosion & breakage, so recommend replacement with every Fuel Tank sale.

SAVE TIME!

TECH TRAYS



**BUY TWO,
GET ONE
FREE!**

Dealer Price **\$99.99**

Order through your local parts distributor

\$50
SAVINGS

**Oil Drain Plug
Tech Tray Promo**

Part # 030-TRAYPROMO

- For a limited time! Promotion expires December 31, 2005
- Buy two trays, get one free
- Promo comes with free Dorman merchandiser and a set of reorder forms
- Oil Drain Plug Tech Tray Promo, part #030-TRAYPROMO

Part No.	Description
030-539	Oil Drain Plug Tech Tray
030-541	Oil Drain Plug Gasket Tech Tray
030-180	Cabin Air Filter Tech Tray FREE

See specific tray information on page 15.



See 2005 Automotive Hardware Assortment Guide # 2500015 for Additional Assortments and Complete Information.



Is the Clock Ticking While You Wait for a Part to Be Delivered?




030-136
Cotter Pins

390 pcs,
12 SKUs




030-611
Wheel Nut Covers

36 pcs,
12 SKUs

60% of Vehicles with Wheel Nut Covers are Missing at Least One.




800-096
QUICK DISCONNECT™
Retaining Clips

26 pcs,
6 SKUs

CONVENIENT!

- Applications Displayed on Inside Cover for Each SKU
- Each Tech Tray Contains a Selection of the Fastest Moving SKUs


<p>Cabin Air Filter Fasteners</p>  <p>030-180</p> <p>105 pcs, 13 SKUs</p>	<p>Vacuum Tees & Connectors</p>  <p>030-496</p> <p>115 pcs, 23 SKUs</p>	<p>Oil Drain Plugs with Gaskets</p>  <p>030-539</p> <p>44 pcs, 22 SKUs</p>	<p>Assorted Oil Drain Plug Gaskets</p>  <p>030-541</p> <p>115 pcs, 20 SKUs</p>
<p>Shop Assortment</p>  <p>030-630</p> <p>260 pcs, 24 SKUs</p>	<p>Push-In Christmas Tree Nylon Fasteners</p>  <p>030-709</p> <p>60 pcs, 12 SKUs</p>	<p>QUICK DISCONNECT™ Connectors & Clips</p>  <p>800-094</p> <p>45 pcs, 7 SKUs</p>	<p>QUICK DISCONNECT™ Connectors Assortment</p>  <p>800-095</p> <p>12 pcs, 12 SKUs</p>
<p>Fuel Line & Sending Unit Repair</p>  <p>800-299</p> <p>8 pcs, 6 SKUs</p>	<p>Distributor O-Rings</p>  <p>80021</p> <p>60 pcs, 12 SKUs</p>	<p>Coolant O-Rings</p>  <p>80022</p> <p>60 pcs, 12 SKUs</p>	<p>Service Dealer Assortment</p>  <p>515700</p> <p>128 pcs</p>

Visit us at www.DormanProducts.com ■ Call Our New Product Hotline 1-800-336-3575

MARKET LEADING COVERAGE

OIL COOLER LINE ASSEMBLIES

Direct Fit OE Replacements



- Includes everything needed to install: O-rings, gaskets, and connector retaining clips



- Premium CSM rubber hoses help prevent premature crimp failure
- Aluminum tube construction increases life of cooler line



A little leak could mean a big problem down the road. Install a new Dorman Oil Cooler Line Assembly at the first sign of trouble.

TECH TIP

INSPECT OIL COOLER LINE CRIMPS AT EVERY OIL CHANGE.

TRANSMISSION LINE ASSEMBLIES



- Market leading 195 Transmission Lines available in 2005
- Comprehensive import and late model coverage




Check out our OE Solutions Catalogs or www.DormanProducts.com for complete application information.



HEATER HOSE ASSEMBLIES

Dorman® OE Solutions™ Heater Hose Assemblies are made from a high temperature, long lasting quality hose with corrosion-resistant steel

- Direct Fit OE Replacement




HELP!

You no longer have to purchase these parts from the OE Dealer.


TAIL LAMP CIRCUIT BOARDS AND HARNESSSES

70001
Blazer, Tahoe, Yukon, Suburban C & K Series Pickup 2000-88




CIRCUIT BOARDS

70002
Stratus, Cirrus, Breeze 2000-95




70004
Malibu 2004-97




Both Sides For The Price Of One!

70005
Maxima 1991-89




Available July

70006
S-Series Blazer 2004-02




70010
GMC Envoy 2004-02




HARNESSES


70015
GM G-Series Vans 1999-96



70017
GM G-Series Vans 2002-00



70007
Nissan Quest & Mercury Villager 1995-93



OE ALTERNATIVE

4WD SWITCH *Direct OE Replacement*

49175
GM S/T Series Trucks 1997-94



- Switch engages 4WD
- Once switch fails, 4WD is inoperable

OIL FILTER CAP *Direct OE Replacement*

82563
GM 2.2L 2005-02



- Dealer only sells with filter as complete assembly
- Plastic design fails when over tightened

WINDOW PARTS

45345
Window Glass Clips
Dodge 2004-02



74444
Window Track Guides
Chevrolet various applications 1996-76



49272
Power Window Switch Clips
Chevrolet various applications 1999-76



Qty: 5

UPPER SHOCK INSULATORS

31020
GM 2004-99



Designed With a Durable Pilot Ring to Prevent Annoying Front End Rattle Or Squeak

Includes 2 Pieces To Service Both Shocks

HELP! BODY PARTS

LICENSE PLATE LENS

68150
GM Trucks 2004-99



FUEL DOOR SPRING

Door will stay open if latch is broken

47208
Toyota Cars & Trucks



HATCH DOOR BUMPERS


45390
Jeep Cherokee 2001-93

Qty: 2



REAR DOOR CHECK STRAP

38449
GM Suburban, Escalade, Yukon, Tahoe 1999-92



ROOF LAMP & HOUSING KIT

69995
GM C & K Series Trucks

Contains housing, lens and screws



THIRD BRAKE LAMP

70008
GM S-Series Blazer, Jimmy, Bravada 2004-95

EXACT OE FIT



INNOVATIVE PARTS

HELP![®]
Makes Customers for **Life**[™]

*Replace the Piece,
 Not the Assembly*

DOOR HINGE KITS

- Dealer Does Not Sell Separately—Must Purchase Entire Assembly
- Prevent Costly Hinge Assembly Damage by Replacing Worn Bushings and Pins



38438
 Various Ford Applications
 2002-91

Average OE Wholesale Price	HELP! Piece Wholesale
\$58.58	\$7.01



38439
 Jeep Cherokee
 1999-1994

Average OE Wholesale Price	HELP! Piece Wholesale
\$34.46	\$7.01

ALSO AVAILABLE:



#38446 GM Full-Sized Vans 2004-96

A/C BYPASS PULLEY




34152
 GM Trucks
 1995-88

More Applications Available

Replace A/C Compressor LIST & LABOR	Install HELP! Bypass Pulley LIST & LABOR
\$750	\$150

HELP!
 Piece Wholesale
\$35.53



Problem

- Torn Serpentine Belt
- Seized A/C Compressor Renders Car Inoperable
- 10 Year-100,000 Mile Vehicle Worth Only \$1,000-\$2,000
- Customer Can't Afford Complete Repair

Options

- Replace A/C Compressor
LIST & LABOR \$750
- Bypass Compressor With Short Belt If Even Possible

Solution

- Remove A/C Compressor
- Install New **HELP!** A/C Bypass Pulley and OE Size Belt
LIST & LABOR \$150

PCV ELBOW



46017
 Ford Truck
 1998-97

Average OE Wholesale Price	HELP! Piece Wholesale
\$32.64	\$9.72

- Fits Ford Trucks
- Dealer Does Not Sell Separately—Must Purchase Entire Hose Assembly
- Replacing Faulty PCV Hoses Improves Engine Performance and Fuel Mileage

FUEL PRESSURE REGULATOR



55162
 GM 4.3L
 Vortec[®] Engines (Vin W)
 1995-93

Average OE Wholesale Price	HELP! Piece Wholesale
\$356.00	\$50.00

Vortec[®] is a registered trademark of General Motors Corporation.

SEAT RELEASE LEVER

- Dealer Does Not Sell Separately—Must Purchase Entire Assembly
- Repairs Seats with Broken Recliner Handles
- Kit Includes Both Driver's and Passenger's Seat Handles



74315
 Ford Explorer
 2001-97

Average OE Wholesale Price	HELP! Piece Wholesale
\$52.82	\$10.97


"OE EXCLUSIVE" PARTS

PRE-FORMED PCV

- Check PCV Tube with Every Engine Disassembly



Old PCV on car looks OK.



Upon closer inspection, cracks are evident.

ALSO AVAILABLE:
Vacuum Connector



47096
Ford

FUEL INJECTOR "O-RING" KIT



- Replace Every Time Injector Is Removed
- Assortment Includes Two Different O-Ring Kits—32 Pieces Total
- Priced Less than One Kit From the OE Dealer

TRANSMISSION CAPS

- Must Be Replaced With Every VW Transmission Fluid Change
- Cap is Designed to Break When Removed



49335
VW 2004-93

PROTECT YOUR CUSTOMER

DO THE JOB RIGHT THE FIRST TIME!

VACUUM RETAINER/BUSHING



47099
Ford
2005-93



- Replace When Working on Intake Manifolds
- Replace Worn Bushings to Maintain Engine Performance and Fuel Economy


EGR GASKET WITH SCREEN



47007
Chevrolet Linear
2003-92, Ford
1993-80

- Replace Every Time EGR Valve Is Serviced
- OE Does Not Include Screen When Replacing Valve
- 3 OE SKUs Are Replaced By 2 Pieces For Less Than Cost of 1

BRAKE CALIPER BOLTS



13898
Ford
Explorer
2001-91



13899
Regal, Lumina,
Monte Carlo,
Grand Prix,
Cutlass Supreme 2001-88

- Mounts Bracket to Spindle
- Replace Each Time Rotor Is Replaced
- Star Drive Bolt Heads Often Round Out During Removal
- Recommend New Bolts to Your Customers When Installing GM W-body Brake Pads

Visit us at www.DormanProducts.com ■ Call Our New Product Hotline 1-800-336-3575

POPULAR HELP! PARTS

BEST OF HELP!

STEERING SENSOR

31025
GM Cars & Trucks
2004-94



■ Driver Experiences A Light Feel in the Steering Wheel When this Part Falls

SPARK PLUG BOOT ADAPTER

49808

Cavalier 2002-95, Beretta 1995-90,
Alero 2001-99, Skylark 1998-88,
Grand Am 2001-88, Malibu 1999-97,
Achieva 1998-92, Cutlass Calais
1991-88, Supreme, Sunfire 2002-95



Get Two For The Price Of One

■ Replace At Tune-Up Time

EMERGENCY BRAKE HOLD-DOWN SPRING

13986
GM Fullsize
Pickups 2004-99,
Full-Size Vans 2004-03
Kit includes 2 Spring
Clips And Screws

■ Easily Damaged
During Brake
Service



HINGE PIN & BUSHING KITS

38437
GM C & K
Series Pickups
2004-99



DOME LIGHT SWITCH

49204
Ford Cars & Trucks
Taurus, Sable
Expedition,
F-Series Pickup,
Ranger, Windstar,
Navigator,
Continental,
Mark IV 2004-95



CMFI FUEL RETURN LINES

55163
Astro, Safari,
S-Series, Blazer,
Jimmy, Sonoma,
Typhoon, Bravada
w/4.3L 1995-92
(Vin W)



55162 Fuel Pressure Regulator
GM 4.3L Vortec® Engines (Vin W) 1995-93

HEATER BYPASS TUBE

56399
Chrysler
3.9L, 5.2L & 5.9L
2003-92

Replace With
Every Water Pump

THIRD BRAKE LAMP SOCKET

70003
Ford Explorer
& Aerostar



Socket Not Sold Separately At OE

FUEL FILTER CAP & GASKET

Guarantees Correct Fit When Servicing Fuel Filter

55851
Ram 2500-3500
w/5.9L Diesel
Engine 2004-02

55850
E, F-Series,
Excursion w/7.3L
Diesel Engine
2004-98



■ Redesigned
With Hex
For Easier
Removal &
Installation

ELBOW WITH O-RING SEAL

47065
GM 3.8L
2005-95

Contains
Two in a Kit

PLASTIC

■ Includes Upper and
Lower Elbows
(Intake to Tensioner)





COMING SOON




HELP! 50 NEW SKUs

MAF Sensor Screw Kit

- Enables removing & cleaning of tamperproof mass air flow sensor



Fuel Cap Tether



- Replaces broken fuel cap tether with one universal kit

Maintenance Tags



- Attaches to parts displaying month & year service was performed

POWER WINDOW SWITCHES



- Many new switches for the latest applications, including popular domestic (GM/Chrysler) & import (Honda, Nissan & Toyota) models
- Master switches w/window lockout & one-touch-down features

A/C BYPASS PULLEYS



- Based on your input, we're adding these new applications:
Chevrolet Camaro and Firebird 1995-88
Chrysler, Dodge & Plymouth Minivans 2000-90
Chevrolet/GMC Trucks, Pickups, Vans and Minivans 2002-92
Ford Mustang 1995-94

MIRROR ASSEMBLIES

New Category



- Direct OE Replacement
- Domestic and Import Coverage
- Keep full door assemblies intact, sell just the needed part

BRAKE CALIPERS



- Chevrolet Trailblazer, GMC Envoy 2004
- Oldsmobile Bravada, Buick Rainier 2004-02
- Chrysler PT Cruiser 2005-01
- Nissan Altima 2005-02

NEW TO THE AFTERMARKET

Wiper Transmissions

- An addition to our wiper program that includes new motors, linkage bushings, wiper arms and pulse boards



- Jeep Cherokee 2001-94
- Dodge Truck Ram Series Pickups 2002-94
- GMC Truck C & K Series Pickups 2002-98

Temperature Actuators



- Every vehicle has one, sometimes two!
- Direct OE Replacement

IGNITION DISTRIBUTOR LINE EXPANSION



- 17 new distributors
- Coverage leader in 100% new ignition distributors

For Complete Applications, See Our **NEW** Catalog Supplements!

Over
2,000
New Reasons
Not to Call the
OE Dealer!



To find out more about
our products, call
1-800-336-3575
or visit our web site,
www.DormanProducts.com

Para averiguar más acerca
de nuestros productos, por favor
llame sin cobro al 1-800-336-3575
o bien visite nuestra página web
www.DormanProducts.com

©2005 R&B, Inc.
No reproduction in whole or part
without prior written approval of R&B, Inc.
www.DormanProducts.com

2300024
Service Dealer
Guide
2003



2400032
Service Dealer
Guide
2004

2500028